

Errata Sheet

ALT-8000 Operation Manual (p/o 88035)

EXPORT CONTROL WARNING: This document contains controlled technology or technical data under the jurisdiction of the Export Administration Regulations (EAR), 15 CFR 730-774. It cannot be transferred to any foreign third party without the specific prior approval of the U.S. Department of Commerce, Bureau of Industry and Security (BIS). Violations of these regulations are punishable by fine, imprisonment, or both.

NOTICE

The following items are applicable to S/W release:
0.0.9 July 22, 2011

ERRATA STATEMENTS (Items to be addressed in Phase I release):

1. Altitude Indicator Zero feature: Not functional.
2. CDF FMCW Mode: Partially functional at low altitudes (below 1000 feet) on some CDF-FMCW radio altimeters.
3. Auto Detect feature: Certain combinations of valid FM CW signals fail to be detected correctly and testing does not start. Manual selection of Radio Altimeter type (FMCW/CDF/Pulse) is suggested.
4. Ethernet Remote Control Interface status reporting not implemented into 488.2/SCPI.
5. FMCW at low altitudes is out of specification: (100ft and below for Collins LRA-700 and 25-ft and below for Honeywell KRA-405B)
6. UUT measured power levels above +25 dBm are out of tolerance. (typically +30 dBm is .4 dB low and +33 dBm is 3 dB low)

ERRATA STATEMENTS (Items to be addressed in Phase II release):

1. Pulse Mode: Not functional.